#### **ENVIRONMENTAL CHEMISTS**

#### Analysis For Total Metals By EPA Method 200.8

Client ID: M030357
Date Received: 09/25/08
Date Extracted: 09/26/08
Date Analyzed: 09/26/08
Matrix: Water
Units: ug/L (ppb)

Client:
Project:
Lab ID:
Data File:
Instrument:

Alaskan Copper Works PO M03057, F&BI 809273

809273-01 x10 809273-01 x10.039 ICPMS1

Operator: hr

Internal Standard: % Re Germanium

% Recovery: Limit: 87 60

Upper Limit: 125

Concentration ug/L (ppb)

Chromium 335
Nickel 258
Copper 602
Zinc 41.5

#### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Alaskan Copper Works Client: PO M03057, F&BI 809273 Date Received: Not Applicable Project: 09/26/08 Lab ID: Date Extracted: 18-367 mb Date Analyzed: 09/26/08 Data File: I8-367 mb.008

Matrix: Water Instrument: ICPMS1

Units: ug/L (ppb) Operator: hr

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 90 60 125

Concentration
Analyte: ug/L (ppb)

 Chromium
 <1</td>

 Nickel
 <1</td>

 Copper
 <1</td>

 Zinc
 <1</td>

### **ENVIRONMENTAL CHEMISTS**

Date of Report: 09/30/08 Date Received: 09/25/08

Project: Metro Self Monitor, PO M03057, F&BI 809273

## QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 809266-01 (Duplicate)

| Analyte  | Reporting Units | Sample<br>Result | Duplicate<br>Result | Relative<br>Percent<br>Difference | Acceptance<br>Criteria |
|----------|-----------------|------------------|---------------------|-----------------------------------|------------------------|
| Chromium | ug/L (ppb)      | <1               | <1                  | nm                                | 0-20                   |
| Nickel   | ug/L (ppb)      | 1.35             | 1.43                | 6                                 | 0-20                   |
| Copper   | ug/L (ppb)      | <1               | <1                  | nm                                | 0-20                   |
| Zinc     | ug/L (ppb)      | 178              | 180                 |                                   | 0-20                   |

Laboratory Code: 809266-01 (Matrix Spike)

|          |                 |                |                  | Percent        |                        |
|----------|-----------------|----------------|------------------|----------------|------------------------|
| Analyte  | Reporting Units | Spike<br>Level | Sample<br>Result | Recovery<br>MS | Acceptance<br>Criteria |
| Chromium | ug/L (ppb)      | 20             | <1               | 66             | 50-150                 |
| Nickel   | ug/L (ppb)      | 20             | 1.35             | 66             | 50-150                 |
| Copper   | ug/L (ppb)      | 20             | <1               | 65             | 50-150                 |
| Zinc     | ug/L (ppb)      | 50             | 178              | 57 b           | 50-150                 |

Laboratory Code: Laboratory Control Sample

| Analyte  | Reporting Units | Spike<br>Level | Percent<br>Recovery<br>LCS | Acceptance<br>Criteria |
|----------|-----------------|----------------|----------------------------|------------------------|
| Chromium | ug/L (ppb)      | 20             | 104                        | 70-130                 |
| Nickel   | ug/L (ppb)      | 20             | 102                        | 70-130                 |
| Copper   | ug/L (ppb)      | 20             | 107                        | 70-130                 |
| Zinc     | ug/L (ppb)      | 50             | 91                         | 70-130                 |

#### **ENVIRONMENTAL CHEMISTS**

# **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 -- More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover fromprevious sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L. The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 30, 2008



#### **INVOICE #08ACU0930-1**

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M03057, F&BI 809273 - Results of testing requested by Gerry Thompson for material submitted on September 25, 2008.

FEDERAL TAX ID # (b) (6)

| 809273                                      |           | Λ · 1          |                 | SAMPLE (    | CHAIN C         |            |               | TO            | DY   |      | ME_09/a                | 25/0                       | AIY  |
|---|-----------|----------------|-----------------|-------------|-----------------|------------|---------------|---------------|------|------|------------------------|----------------------------|--|
| Company ACASCAL  Address 628 5              |           | _              |                 | PROJEC      | CT NAME/        | NO.        |               | >~c           | CION |      | PO#<br>MO30 <b>3</b> 7 | ☐ Star                     | TURNAROUND TIME adard (2 Weeks) SH charges authorized by:                      |
| City, State, ZIP Seat<br>Phone # 206-571-60 |           |                |                 |             | KS              |            |               |               |      |      |                        | □ Disp<br>□ Retu<br>□ Will | SAMPLE DISPOSAL<br>cose after 30 days<br>arn samples<br>call with instructions |
| Sample ID                                   | Lab<br>ID | låte<br>Sæpled | Time<br>Sampled | Sample Type | # of containers | TPH-Diesel | TPII-Gasolino | BTEX by 8021B | 8260 | 8270 | OR CLANT CATANATA      | ED                         | Notes  |
| M030357                                     | 01        | 9/25/08        | 11:30           | Azo         | 1               |            |               |               |      | 7    |                        | 7)                         |  |

|                        |    |         |       |            |            | -      | 뒤   | BT | <b>X</b> | S | 13 |     |      |    |   |      |      |
|------------------------|----|---------|-------|------------|------------|--------|-----|----|----------|---|----|-----|------|----|---|------|------|
| M030357                | 01 | 9/25/08 | 11:30 | Are        | 1          |        |     |    |          |   | N  |     |      | 7: |   |      |      |
|                        |    |         |       |            |            |        |     |    |          |   |    |     |      |    |   |      |      |
|                        |    |         |       |            | 191<br>191 |        |     | ,  |          |   |    |     |      |    |   |      |      |
|                        |    |         |       |            |            |        |     |    |          |   |    |     |      |    |   |      |      |
|                        |    | , II    |       |            |            |        |     |    |          |   |    |     |      |    |   | *    |      |
| 3                      |    |         |       |            |            |        |     |    |          |   |    |     |      |    |   |      |      |
| ×                      |    |         |       |            |            |        |     |    |          |   |    |     |      |    |   |      |      |
|                        |    |         |       |            |            | , etc. |     |    |          |   |    |     | 2/   |    |   |      | 1.12 |
|                        |    |         |       | N. Company |            |        |     |    |          |   |    |     |      |    |   |      |      |
| 9                      |    |         |       |            |            |        |     |    |          | I |    |     |      |    |   |      |      |
| Friedman & Bruya, Inc. |    | Sign    | ATURE | 7          | p.         | RINT   | 'NA | ME |          |   | T  | COM | ΡΛΝΥ | -  | T | DATE | TIME |

3012 16th Avenue West

Seattle, WA 98119-2029

Ph. (206) 285-8282

Fax (206) 283-5044

| FORMS\ | COC | COC | DOC |
|--------|-----|-----|-----|

| PRINT NAME     | COMPANY      | DATE                 | TIME                         |
|----------------|--------------|----------------------|------------------------------|
| = Genso Tarpor | ALL .        | 9/25/08              | 1:08pm                       |
| Whan Phan      | FeBI         | 9/05/cx              | 1:08                         |
|                | ε το α       |                      |                              |
|                |              |                      |                              |
|                | Sense Tarpor | Scensor Transpor ACL | Scensor Transpor ACL 9/15/08 |

Samples received at 18 °C

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 30, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on September 25, 2008 from the Metro Self Monitor, PO M03057, F&BI 809273 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0930R.DOC